




REVOLUTION

HELICOPTER CORP., INC.



1905 W. Jesse James Rd. * Excelsior Springs, Missouri 64024
Phone (816) 637-2800 * Fax (816) 637-7936

September 23, 1999

Dear Valued Customer,

During our continuous testing and improvement program here at Revolution Helicopter, we have determined the need to issue two different Airworthiness Directives concerning the Main and Tail Rotor transmissions. In order to reduce down-time, we are issuing both AD's to be complied with at the same time.

There is a **time-to-comply** on one of the AD's, so please make sure you read, understand and follow it. If not, then a higher price will need to be charged for future compliance.

It is highly recommended that all Mini-500 owners comply with these, and all AD's, to ensure the proper operation of your helicopter.

Also, we are issuing another warning concerning the engine carburetor jetting. This warning also gives further information on what RHCI has recently compiled about jetting, and should give you an easier guideline to follow.

If you have sold your Mini-500, please forward these AD's to the new owner, or give RHCI their name and address and we will contact them. If you have any questions concerning these AD's, please contact RHCI Customer Service at (816) 637-2800.

Sincerely,

Customer Service
Revolution Helicopter Corp.