



**REVOLUTION**  
HELICOPTER CORP., INC.



1905 W. Jesse James Rd. • Excelsior Springs, Missouri 64024  
Phone (816) 637-2800 • Fax (816) 637-7936

April 24, 1996

Service information letter #033196

Subject: Tail wiring harness

Applicability: All Mini-500's

This letter is to emphasize the fact that the wiring harness in the tail boom must be secured.

Holes are provided in the tail boom for securing the tail wiring harness and the tail rotor control cable. You must insure that you capture all the wires and the control cable with the cable tie.

If any of the wires are left loose, the wire could snag on the tail rotor drive shaft. At a minimum this will destroy the wire harness. In the worst case, total loss of tail rotor control could result.

On each preflight, inspect the cable ties to insure that they are not broken allowing the wires to become loose.

Please print your name and date, then mail or fax a copy of this letter to Revolution Helicopter before May 15, 1996.

Name: \_\_\_\_\_

Date: \_\_\_\_\_

If you have any questions please contact Brian Thomas at (816) 637-2800.