



REVOLUTION
HELICOPTER CORP., INC.



1905 W. Jesse James Rd. * Excelsior Springs, Missouri 64024
Phone (816) 637-2800 * Fax (816) 637-7936

Subject: Bravo Assembly Drawing & Upgrade Parts List

Many of the owners have requested an updated drawing concerning the Mini-500 Bravo Rotor Head Assembly. The updated drawing will reduce the confusing and be added to the assembly manual at some date in the near future.

The confusion was caused because the new pitch arm #0011 is cast, not stamped and zinc plated. A slightly longer bolt #0369 is included to secure the adjustable pitch length hardware. The adjustable turn buckle #0032 is slightly longer. Two flat spacer washers were replaced with a recessed washer # 0744.

Thank you for your patient. We apologize for the delay in sending this information to you.

Rick Stitt
Project Engineer/Customer Service