



# **REVOLUTION**

**HELICOPTER CORP., INC.**



1905 W. Jesse James Rd. • Excelsior Springs, Missouri 64024  
Phone (816) 637-2800 • Fax (816) 637-7936

July 12, 1996

Service information letter #071296

Subject: Vertical Stabilizer Bolts

Applicability: All Mini-500's

Some early number kits were shipped with (4) bolts #0389 that are too short. These bolts are the ones that mount the vertical stabilizer to the tail rotor gear box. Remove one of these bolts from the helicopter and use the AN bolt gauge in section 1 page 5 of your assembly manual to check the length. The bolt should be an AN4-17. If you have bolts of the wrong length, send them to Revolution Helicopter, along with a copy of this letter, for replacement.

We must receive your bolts before August 15, 1996 for the warranty to apply.

Name: \_\_\_\_\_

Date: \_\_\_\_\_

If you have any questions please contact Brian Thomas at (816) 637-2800.