



REVOLUTION
HELICOPTER CORP., INC.



1905 W. Jesse James Rd. * Excelsior Springs, Missouri 64024
Phone (816) 637-2800 * Fax (816) 637-7936

July 22, 1999

Service Information Letter #072299

Subject: Transmission to Frame Continuity

1. In a normal Mast Support installation the isolation of the transmission from the frame has been found to interfere with main transmission chip detector operation and contributes to radio noise.
2. Mast support customers are advised to fabricate a grounding wire from one of the main transmission case bolts to the frame to alleviate this difficulty.

If you have any questions about this procedure, contact us at (816)-637-2800.