



REVOLUTION
HELICOPTER CORP., INC.



1905 W. Jesse James Rd. • Excelsior Springs, Missouri 64024
Phone (816) 637-2800 • Fax (816) 637-7936

October 2, 1995

Service information letter #093095

Subject: #BA19

Some kits were mistakenly sent out with (2) of part number BA20 and no part number BA19.

Look at VP card 11, and find part #BA19. This part should have (4) 1/4" holes in the round tube base. If the part has a key way in the round tube base and no 1/4" holes, then it is the wrong part.

If you have the wrong part, please send it back to Revolution Helicopter undamaged and we will send you the correct part.

If you have any questions please contact Brian Thomas at (816) 637-2800.