




# **REVOLUTION**

**HELICOPTER CORP., INC.**



1905 W. Jesse James Rd. • Excelsior Springs, Missouri 64024  
Phone (816) 637-2800 • Fax (816) 637-7936

April 24, 1996

To: All Mini-500 owners

Subject: Revolution Airworthiness Directives and Service Information Letters

As part of our ongoing commitment to customer support, Revolution Helicopter has put into place a system to keep you informed of any changes to the building or operating procedures of the Mini-500.

This system consists of two types of advisories, Airworthiness Directives and Service Information letters. An Airworthiness Directive (AD), will be issued for issues that would effect safety of flight. Remember, these AD's are issued by Revolution Helicopter and not the Federal Aviation Administration. A Service Information Letter (SIL) will be issued for such things as, to clarify a section of the assembly manual or to inform you of common mistakes that are being made in the field.

This service is provided for the benefit of you the customer and all advisories should be complied with.

Brian Thomas  
RHCI